Software History

NOTE: Each release contains all solutions identified in the earlier version. The latest software solves the issues below:

TPN141L 026.003.046.128 (Date published: 2016-08-15)

• Improvement in HUE Bridge not recognized in the TV Set

TPN141L_026.003.042.128 (Date published: 2016-03-23)

- PQ issue (greenish edge @ some part of screen).
- Picture format issue.

TPN141L_026.003.032.128 (Date published: 2015-10-27)

- TV does not response to remote control command issue.
- No image in HDMI mode issue.

TPN141L_026.003.030.128 (Date published: 2015-08 -18)

- YouTube connectivity issue.
- Hidden Wi-Fi does not connect issue.

TPN141L 026.003.026.128 (Date published: 2015-03-19)

- Change the video format behavior of Autofill item.
- Update NETFLIX app software.

TPN141L_026.003.022.128 (Date published: 2015-02-14)

- Set does not record in standby Mode.
- Picture quality improved.

TPN141L_026.003.018.128 (Date published: 2014-11-14)

- To improve audio effect of USB source.
- Joysticker (Volume setting) behavior change.

TPN141L_026.003.010.128 (Date published: 2014-10-14)

- Skype update.
- EDFU content modifies.
- Fix issue: Lip sync issue when connect to set top box with HDMI.

TPN141L_026.003.002.128 (Date published: 2014-08-20)

• To solve SMART TV connectivity issue.

TPN141L_026.002.004.128 (Date published: 2014-06-06)

- Remote control pointer function implements.
- Netflix translation issue fixed.
- Worldcap app functions implement.

TPN141L_026.002.002.128 (Date published: 2014-03-01)

• Initial production software.