Software History

NOTE: Each release contains all solutions identified in the earlier version.

TPM215L_001.002.053.001 (Date Published: 03 Oct 2022)

- TV power on with no image, only back light on due to data corruption issue.
- Wrong audio language selection in specific DTV programs.
- Missing DTV channels in country Peru.
- Backlight adjustment in picture menu not working after playing Dolby Vision video.
- Memory optimization
- User menu update

TPM215L_001.001.250.002 (Date Published: 21 Jun 2022)

- Youtube / Netflix have sound but no picture issue.
- Wifi driver update.
- User manual update.

TPM215L_001.001.201.001 (Date Published: 5 Apr 2022)

- TV cannot power on after overnight standby at times.
- Screen mirroring fails to connect at WiFi 5Ghz band.
- TV loss sound from TV speaker after switching source between cable set top box and PS4.
- Support Ginga-D application.
- Not able to turn on WIFI when internet cable (RJ45) is connected to the TV set.

TPM215L_001.001.109.000 (Date Published: 24 Nov 2021)

• HBO_Max App auto exit when start to play any video.

TPM215L_001.000.211.011 (Date Published: 16 Jul 2021)

• First software release.