Software History

NOTE: Each release contains all solutions identified in the earlier version.
The latest software solves the issues below:

TPN142L_026.003.032.128 *(Date published: 2016-08-15)*
- Improvement in HUE Bridge not recognized in the TV Set

TPN142L_026.003.028.128 *(Date published: 2016-03-23)*
- PQ issue (greenish edge @ some part of screen).
- Picture format issue.
-
TPN142L_026.003.018.128 *(Date published: 2015-10-27)*
- TV does not response to remote control command issue.
- No image in HDMI mode issue.
- Discolor shadow on the left of some images.

TPN142L_026.003.010.128 *(Date published: 2015-03-19)*
- Change the video format behavior of Autofill item.
- Update NETFLIX app software.

TPN142L_026.003.006.128 *(Date published: 2015-02-14)*
- Set does not record in Stand by Mode.
- Subtitle position issue via USB video.

TPN142L_026.003.004.128 *(Date published: 2014-10-14)*
- Skype update.
- EDFU content modifies.
- Fix issue: Lip sync issue when connect to set top box with HDMI.

TPN142L_026.002.008.128 *(Date published: 2014-07-21)*
- Initial production software.