

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

**TPM186E\_018.004.083.001** (*Date published: 2018-12-10*)

- Resolve device portal connection issue.
- Resolve the timeshift playback control bar display issue.

**TPM186E\_018.004.029.001** (*Date published: 2018-10-02*)

- E-sticker update.
- UI update for OLED 873 series.

**TPM186E\_018.002.251.001** (*Date published: 2018-09-09*)

- Initial production software.