

Software History

NOTE: Each release contains all solutions identified in the earlier version.
The latest software solves the issues below:

TPM144L_V2.107 *(Date published: 2015-07-16)*

- Zoom operates by itself.
- Corrective translation in Portuguese.
- Rattle noise and distortion when play the MP4.

TPM144L_V2.105 *(Date published: 2015-05-27)*

- USB videos with no video format change availability (21:9 content).

TPM144L_V2.103 *(Date published: 2015-02-10)*

- Reboot issue.
- ATV independently of the channel selected, RC command is slow responsive.

TPM144L_V2.0102 *(Date published: 2015-01-22)*

- AVL AQ.bin setting update.
- Channel or Volume auto change.

TPM144L_V2.011 *(Date published: 2014-08-12)*

- Add ARG Ginga function.
- ARG translation update.
- Modify behavior and UI display when select DTVi applications.

TPM144L_V2.007 *(Date published: 2014-04-10)*

- Modify translation.
- Modify spacing, alignment issue.
- Modify auto switch DTV channel after install channel in virgin mode.
- Modify icon of "Satellite receiver" in ISL.

TPM144L_V2.006 *(Date published: 2014-03-20)*

- Initial production software.