

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPS1011A_32PHA4509_V2.03 (*Date published: 2014-04-2*)

Improve AV SECAM picture quality.

TPS1011A_32PHA4509_V2.01 (*Date published: 2014-03-12*)

Initial production software.