

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.  
The latest software solves the issues below:

### **TPM140L\_V2.105** *(Date published: 2015-05-27)*

- USB videos with no video format change availability (21:9 content).

### **TPM140L\_V2.103** *(Date published: 2015-02-10)*

- Reboot issue.
- ATV independently of the channel selected, RC command is slow responsive.

### **TPM140L\_V2.102** *(Date published: 2015-01-22)*

- AVL AQ.bin setting update.
- Channel or Volume auto change.

### **TPM140L\_V2.011** *(Date published: 2014-07-07)*

- Correct e-sticker.
- Correct EPG option icon.

### **TPM140L\_V2.009** *(Date published: 2014-04-10)*

- Modify translation.
- Modify spacing, alignment issue.
- Modify auto switch DTV channel after install channel in virgin mode.
- Modify icon of "Satellite receiver" in ISL.

### **TPM140L\_V2.008** *(Date published: 2014-03-10)*

- Add Ginga and Ginga autostart UI.
- Modify translation in options menu.

### **TPM140L\_V2.007** *(Date published: 2014-02-24)*

- Initial production software.