

Software History

NOTE: Each release contains all solutions identified in the earlier version.
The latest software solves the issues below:

TPM140L_V2.112 *(Date published: 2018-09-26)*

- When TV detecting Ginga signal, audio auto unmute.
- One Touch Play function abnormal.

TPM140L_V2.107 *(Date published: 2015-07-16)*

- Zoom operates by itself.
- Corrective translation in Portuguese.
- Rattle noise and distortion when play the MP4.

TPM140L_V2.105 *(Date published: 2015-05-27)*

- USB videos with no video format change availability (21:9 content).

TPM140L_V2.103 *(Date published: 2015-02-10)*

- Reboot issue.
- ATV independently of the channel selected, RC command is slow responsive.

TPM140L_V2.102 *(Date published: 2015-01-22)*

- AVL AQ.bin setting update.
- Channel or Volume auto change.

TPM140L_V2.011 *(Date published: 2014-07-07)*

- Correct e-sticker.
- Correct EPG option icon.

TPM140L_V2.009 *(Date published: 2014-04-10)*

- Modify translation.
- Modify spacing, alignment issue.
- Modify auto switch DTV channel after install channel in virgin mode.
- Modify icon of "Satellite receiver" in ISL.

TPM140L_V2.008 *(Date published: 2014-03-10)*

- Add Ginga and Ginga autostart UI.
- Modify translation in options menu.

TPM140L_V2.007 *(Date published: 2014-02-24)*

- Initial production software.