

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

**TPM165L\_V026.002.008.001** (*Date published: 2018-09-18*)

- Improvement of Netflix connection issue.
- YouTube to change the root certificate authority for its services.

*\* After software upgrade,*

*1) Press "Settings" key on RC, select "General settings" -> "Reinstall TV."*

*2) Remove the AC power to TV set, wait for a minute and re-apply the AC power to TV set.*

*Note that All settings will be reset and installed channels will be replaced.*

**TPM165L\_V026.002.001.001** (*Date published: 2015-11-07*)

- Initial production software