

Software History

NOTE: Each release contains all solutions identified in the earlier version.

TPM156L_V005.255.041.112 (*Date published: 2018-08-15*)

- 4K format not decoded after Standby (DIRECT TV STB)
- Display black screen when connecting 2160P/60 on HDMI3 port

TPM156L_V005.255.041.111 (*Date published: 2018-04-09*)

- Solves Youtube V2 pinkish screen and Netflix playback with audio but no video

TPM156L_V005.255.041.110 (*Date published: 2018-02-07*)

- Solves no video & audio issue when exit Youtube V2 to Watch TV

TPM156L_V005.255.041.109 (*Date published: 2018-01-26*)

- Solves no video issue when exit Youtube to Watch TV (for 49PUG6801/77 ONLY)

TPM156L_V005.255.041.108 (*Date published: 2018-01-10*)

- Android TV with error message of "Youtube has stopped"
- 4K video not supported in the USB input
- Distorted audio observed during playback in Youtube V2

TPM156L_V005.255.041.107 (*Date published: 2017-10-13*)

- Philips logo abnormal when power on TV
- Black display after TV and Cable channel installed
- Channel Noise line
- Cable no sound and background audio noise in YouTube

TPM156L_V005.255.041.105 (*Date published: 2017-03-22*)

- Improvements in [Netflix]
- Set turning on by itself (wakes up at 3:00 AM)
- Mute in Analog cable when TV is turned off in YouTube
- Audio decoding improvement in TV Broadcast

TPM156L_V005.231.000.100 (*Date published: 2016-08-30*)

- BT Remote Control stop operating after some time
- TV wakes up at 04:00/06:00 AM

TPM156L_V005.231.000.097 (*Date published: 2016-06-15*)

- Improvements in [Netflix]
- Improvements in [Youtube]
- Improvement in source selection (HDMI/Watch TV)
- Improvement in Switch On Timing
- Improvement in Audio Quality
- Improvement in Analog channel installation

- Voice search via Android TV Remote Control APPS
- Power key on Joystick behaves the same as power key on RC