

## **Software History**

**IMPORTANT:** *There is a new improvement made in the new software release to improve the channel search efficiency, which required the TV channels to be reinstalled when you update the TV software from version TPM1012L\_2.06 (or older) to version TPM1012L\_2.09 (or later). After you have reinstalled your TV channels, you can rearrange the channels to suit your preference in the channel grid with the Reorder feature in the options menu.*

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

### **TPM1012L\_2.09** *(Date published: 2014-01-10)*

- Update PVR translation
- To improve TV power sequence of standby mode.

### **TPM1012L\_2.06** *(Date published: 2013-05-13)*

- Initial production software.