

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

### **TPM211EA\_101.001.003.223** *(Date published: 2022-11-09)*

- Audio behaviour aline.
- Fix no video when playback Dolby Vision content on certain 4K Blu-ray player.
- Fix for picture flicker after rebooting XboX
- Improvements for Picture Quality
- Improvements for stability issues (reboots, freezes)

### **TPM211EA\_101.000.178.206** *(Date published: 2022-06-28)*

- Initial Android R.
- Fix for duplicate "Google Play Movies" entries in the source menu.
- Fix for hue propagation delay / response time is too high.
- Fix for HbbTv does not work when IPv6 is enabled on the router settings.
- Fix for picture style don't back to "Monitor" when NB signal restart.

### **TPM211EA\_001.002.114.205** *(Date published: 2022-05-09)*

- Fix for hue light not showing correctly.
- Fix for TV reboot when wifi is connected.

### **TPM211EA\_001.002.095.001** *(Date published: 2022-01-24)*

- Fix for vertical line seen on the right side of the screen eg. OLED screensaver
- Fix for Calman color calibration functionality
- Fix ambilight won't change the color or auto turn on
- Improvements for picture quality
  - Flickering, loss of details, frame drops
  - shadows around moving objects
- Fix for no audio on HDMI eARC
- Fix for audio loss on HDMI eARC
- Fix for auto-wake up due to IR interferences
- Fix for a wrong gradation of the bottom ambilight bar
- Fix for crash in settings menu
- Fix for sound settings not stored or not reset
- Prevention for TV going to factory mode unwanted
- Support for AppleTV pre-installation
- Other general system improvements

### **TPM211EA\_001.001.250.200** *(Date published: 2021-10-15)*

- TV has sound but no picture.
- General system improvement

### **TPM211EA\_001.001.230.001** *(Date published: 2021-08-10)*

- Initial production software.