



Release notes xxHFL2869 – Studio range Software release v1.38.26.0

Category:	Software Release notes
Date:	04 April 2019
Version:	1.0
Status:	Released

Purpose and Scope:

The purpose of this document is to specify the status and contents of software release version v1.38.26.0 concerning the xxHFL2869 Studio range.

1.1 Release Summary

Product	Release	Date
xxHFL2869	v1.38.26.0	4 April 2019

1.2 Release Information

Filename	Current Release	Previous release
VES171HE_upgrade.bin	V1.38.26.0	V1.38.18.0

Software release v1.38.26.0 is available on the official website:

www.philips.com/support

1.3 Resolved problems

Resolved problem v.1.38.26.0

- Build in internal delayed reboot in case of Quick Standby
- General robustness improvements of the platform