Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

T921L_2.10 (Date published: 2012-10-04)

• E-Sticker update.

T921L 2.07 (Date published: 2012-08-30)

• Picture freezes while watching video from Youtube.

T921L_2.04 (Date published: 2012-04-30)

• Improved OSD translation.

T921L 2.03 (Date published: 2012-04-05)

• Initial production software.