

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM152L_026.002.014.001 (*Date published: 2018-03-01*)

- Improvement of Netflix connection issue.

TPM152L_026.002.012.001 (*Date published: 2016-07-18*)

- Improvement on TV not response to remote control issue.
- Improvement on picture format issue.
- Improvement on picture quality issue.

TPM152L_026.002.010.001 (*Date published: 2015-10-21*)

- Slow response to all RC keys when TV start up.
- the SMART TV Portal Demo shows that the SKYPE App is available but Skype is not available in this series.

TPM152L_026.002.007.001 (*Date published: 2015-06-22*)

- Caption service submenu cannot be selected when playback PVR.
- TV cannot play Mpeg-Dash video.
- TV shows black screen when exit to USB mode.
- Set TV network name auto closes UI.

TPM152L_026.002.000.001 (*Date published: 2015-03-27*)

- Initial production software for H & T models.