

## Software History

**NOTE:** Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

### **TPM179E\_012.002.246.001 (Date published: 2020-12-16)**

- Resolve MDS data memory issue.
- Latency setting not remembered in Game and monitor picture style after TV wakes up from standby.
- Image blinking when playback 4K HDR contents.
- Netflix error TVQ-PM-100 (5.2.102) due to incorrect NTP Time Acquisition.
- flipped picture / mirrored image /no image / hang up due to corrupted data in NVM.
- Lip sync issue on DVB-S channel via HDMI set top box.
- "No signal" appears on HDMI source after exiting from Miracast connection.
- Philips Server not found due to IPv6 DNS Query fail.
- TV starts the standby shutdown counter after launching Amazon Prime Video.
- Internet browser cannot login Google account.
- Youtube livestream video stuck in "loading" phase after 30min playback duration.
- Unable to connect to (mesh) network.

### **TPM179E\_012.002.230.001 (Date published: 2019-11-11)**

- Smart TV apps (Chili, All4, Demand5, iplayer) not starting.
- Delta volume setting not stored.
- Netflix hung up when switching to DTV while Netflix video is still loading.
- TV hang up, no response to remote control or auto wake up in specific condition.
- General Stability improvement.

### **TPM179E\_012.002.223.001 (Date published: 2019-04-24)**

- Resolve smart TV portal connection issue related to IPv6 DNS query.
- Resolve SmartTV apps cannot be operated while Chromecast is connected to HDMI port issue.
- Picture format issue when playing video with some Smart TV Apps
- Resolve ambient light brightness setting not remembered when TV wakes up from standby issue.
- Resolve ambient light switches on in screen off mode issue.
- Resolve Delta volume setting not stored issue.
- Resolve TV auto wake up and lost favorite channels issue.
- Resolve Start Netflix with only black screen issue.
- Resolve Prime Video playback freezing issue.
- Improvement on WIFI scan find no routers issue.

### **TPM179E\_012.002.206.001 (Date published: 2018-10-17)**

- Resolve YouTube video volume changed issue
- Resolve HDMI PC input time lag issue.
- Resolve USB 2.0 HDD not recognized issue.
- Resolve TV auto wake up or not able to wake up from standby due to wifi module firmware blocked issue.

### **TPM179E\_012.002.182.001 (Date published: 2018-05-23)**

- Netflix error TVQ-PM-100 issue (If Netflix error already seen before software update, please do a re-install TV, remove the AC power to TV set, wait for a minute and re-apply the AC power to the TV set.)
- Resolve USB HDD detection and video playback issue.
- Improvement in Miracast connection issue.
- Resolve Megogo App issue.
- Resolve ambilight issue.
- Resolve original video format cannot do zoom/stretch issue.

**TPM179E\_012.002.165.001 (Date published: 2018-03-19)**

- Resolve HDMI Computer mode input lag issues.
- Improve PQ with PS4 Pro / Xbox.
- Resolve Miracast connection issues.
- Enable support of v2.0 HbbTV.

**TPM179E\_012.002.132.011 (Date published: 2017-11-30)**

- Resolve network and smart TV connection issues.

**TPM179E\_012.002.132.001 (Date published: 2017-11-02)**

- Whitelist data update
- Enable Amazon Video App

**TPM179E\_012.002.108.001 (Date published: 2017-09-20)**

- Resolve channel banner shaking issue when changing from other source inputs to TV
- TV does not start playing Demo me video in shop mode after mains power off and on.
- UI improvement.

**TPM179E\_012.002.070.011 (Date published: 2017-08-03)**

- Improvement on General & Freeview Play Stability
- Improvement on Ambilight – Follow Audio performance
- Resolve switch off timer issue in smart TV operation.

**TPM179E\_012.002.047.001 (Date published: 2017-07-19)**

- Improvement on stability
- Channel logo update
- Resolve navigation issues in “Catchup TV”

**TPM179E\_012.002.028.021 (Date published: 2017-07-05)**

- Initial production software.