

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM202A_001.001.073.000 (*Date published: 2022-05-24*)

- Improved router compatibility.

TPM202A_001.001.051.000 (*Date published: 2022-03-23*)

- Screen corruption when TV turn on.
- Screen mirroring function support 5GHz wifi
- General system improvement

TPM202A_001.001.018.000 (*Date published: 2021-10-07*)

- TV auto turn on.
- General system improvement

TPM202A_001.000.182.001 (*Date published: 2020-07-30*)

- Initial production software.