

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPM186K_058.004.160.021 (*Date published: 2019-05-16*)

- When switch favourite channel up/down, the order is random.

TPM186K_058.004.136.001 (*Date published: 2019-03-25*)

- Switch channel behaviour modified.
- [Smart TV] connection issue related to IPV6 DNS query.
- [OLED] TV does not show message before going to standby for clear residual image.

TPM186K_058.004.088.001 (*Date published: 2019-01-23*)

- [OLED] Off-RS function update in shop mode.

TPM186K_058.004.063.001 (*Date published: 2018-11-22*)

- Improve the lip sync when playing some USB video with audio out from TV speaker.

TPM186K_058.004.011.001 (*Date published: 2018-09-09*)

- Initial production software.